

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	5	((Blumberg near2 Manfred) (Dirrichs near2 Stefan) (London near2 Wolfgang) (Topfer near2 Gary)).in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:24
S2	1	((Blumberg near2 Manfred) (Dirrichs near2 Stefan) (London near2 Wolfgang) (Topfer near2 Gary)).in. AND (machine near tool with encod\$4).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:25
S3	1	(726/27.ccls.) AND (machine near3 tool).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:26
S7	5	("726"/\$.ccls.) AND (machine with tool with (encod\$4 encrypt\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:28
S9	15	("713"/\$.ccls.) AND (machine with tool with (encod\$4 encrypt\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:29
S10	1514	(prevent\$4 with (operating operation control\$4) with (machine near2 tool))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/07/24 18:31
S11	2	((prevent\$4 avoid\$4 prohibit \$4 authoriz\$4 authenticat \$4) near7 (operat\$4 control \$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4)) with (encrypt\$4 encod\$4 \$4cipher\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 08:43

S12	12	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4) near7 (operat\$4 control\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same (encrypt\$4 encod\$4 \$4cipher\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 08:57
S13	24	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same (encrypt\$4 encod\$4 \$4cipher\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:01
S15	34	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with (machine near2 (tool drill\$4 grind\$4 mill\$4 lath\$4 CNC)) same ((encrypt\$4 encod\$4 \$4cipher\$4) password (decrypt\$4 decod\$4))) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:03
S17	32	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with ((machine device) near2 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:10
S18	36	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) with (operat\$6 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:11

S19	67	((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4\$proper\$4) with (operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:12
S20	33	S19 not S15	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:12
S21	1165	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:22
S22	626	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine device) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23
S23	531	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4 password)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23
S24	525	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$\$ decrypt\$4 decod\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:23

S25	243	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:24
S26	61	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4).ab.) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:24
S27	87	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4)) AND (@ad<"20031017") AND (operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)).ab.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28
S28	102	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4)) AND (@ad<"20031017") AND (operat\$6 activat\$4 control\$4 work\$4 start\$4) with	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28

		((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)).clm.				
S29	68	S27 not S26	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:28
S30	33	S28 not S27	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/15 09:34
S31	243	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe \$4 harzard\$4)) AND (@ad<"20031017") AND (operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:48
S32	243	((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe \$4 harzard\$4)) AND (@ad<"20031017") AND ((operat\$6 activat\$4 control \$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:51

S34	2	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$4 decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4)) AND (@ad<"20031017") AND ((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod\$4 decod\$4 \$4cipher\$4) same key)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:52
S35	6	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$4 decrypt\$4 decod\$4)) AND ((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod\$4 decod\$4 \$4cipher\$4) same key) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:53
S36	6	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher\$4 decrypt\$4 decod\$4)) AND (((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) same (encrypt\$4 decrypt\$4 encod\$4 decod\$4 \$4cipher\$4) same key) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55

S37	41	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 ecrypt\$4 encod\$4 decod\$4 \$4cipher \$4) same key) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55
S38	38	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 ecrypt\$4 encod\$4 decod\$4 \$4cipher \$4) with key) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:55
S39	10	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((encrypt\$4 ecrypt\$4 encod\$4 decod\$4 \$4cipher \$4) with key) AND (@ad<"20031017") AND (not Ginter.in.)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 11:57
S40	6	("4405829" "4981402"). PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/16 15:16
S41	28	((operat\$6 activat\$4 control\$4 work\$4 start\$4) with ((machine) near5 (tool drilling grinding milling lath\$4 CNC threading)) with (encrypt\$4 encod\$4 \$4cipher \$\$ decrypt\$4 decod\$4)) AND ((prevent\$4 avoid\$4 prohibit\$4 authoriz\$4 authenticat\$4 protect\$4 safe\$4 harzard\$4) same (public near2 key)) AND (@ad<"20031017")	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:37

S45	265	(((machine) near5 (tool drilling grinding milling lath \$4 CNC threading)) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad<"20031017"))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:45
S46	80	((control\$4 operat\$4 activat\$4 start\$4) with (machine near5 (tool drilling grinding milling lath\$4 CNC threading))) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (@ad<"20031017"))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:46
S48	52	((control\$4 operat\$4 activat\$4 start\$4) with (machine near5 (tool drilling grinding milling lath\$4 CNC threading))) AND ((public near2 key) with (encrypt\$4 decrypt\$4)) AND (not S41) AND (@ad<"20031017"))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 08:47
S49	1	10/575524	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/06/19 11:14

6/ 19/ 2009 4:29:06 PM

C:\ Documents and Settings\ lpham7\ My Documents\ EAST\ Workspaces\ 10\ 10-575-524.wsp